

# Navy Super Hornet Crashes in Philippine Sea; Crew Rescued

PHILIPPINE SEA – A Carrier Air Wing 5 (CVW-5) F/A-18F experienced a mechanical issue that resulted in the crew ejecting while conducting routine operations in the Philippine Sea Nov. 12, Task Force 70 public affairs said in a release.

“The crew was immediately and safely recovered by USS Ronald Reagan search-and-rescue aircraft and brought back to the ship for evaluation by medical personnel, the release said. “Both aviators are in good condition.”

The F/A-18F was flown by Strike Fighter Squadron 102, one of four Super Hornet squadrons assigned to Carrier Air Wing Five.

Two other CVW-5 aircraft have been lost in mishaps over the past year. On Nov. 22, 2018, a C-2A Greyhound assigned to Fleet Logistics Support Squadron 30 Detachment Five crashed into the Philippine Sea while en route to Ronald Reagan, killing three Sailors. On Oct. 19, an MH-60R Seahawk assigned to Helicopter Maritime Strike Squadron 77 crashed on the flight deck of the carrier, injuring 12 persons.

CVW-5 is embarked onboard Ronald Reagan and is currently underway in the U.S. 7th Fleet area of operations in support of security and stability in the Indo-Pacific region.

Ronald Reagan has resumed normal operations and the crash is under investigation.